

**Revised LIST OF SOUTH BOUND CRASH BARRIER DEFECTS**

	COMPLETED	
	NAME	DATE
<b>North East Side Span</b>		
1. P.P. 12 N.E. MALE END HOLED.		
2. P.P. 19-20 N.E. BENT POST (PREVIOUSLY RECORDED).		
<b>North East Main Span</b>		
3. P.P. 56 N.E. MALE END HOLED (UNDERSIDE).		
4. P.P. 62 N.E. MALE END HOLED (UNDERSIDE).		
5. P.P. 86 N.E. POST BASE CRACKED.		
6. P.P.88 N.E. POST BASE CRACKED (FOUR SIDES OF BASE).		
<b>South East Main Span</b>		
7. P.P. 68 S.E. MALE END HOLED (UNDERSIDE).		
8. P.P. 62 S.E. POST BASE CRACKED.		
<b>South East Side Span</b>		
9. P.P. 30 S.E. MALE END SHEARED (OUTSTANDING).		
10. P.P. 28 S.E. MALE END HOLED.		
11. P.P. 22 S.E. POST DAMAGED/WELD BROKEN (OUTSTANDING).		
12. P.P. 12 S.E. REPLACE MALE & FEMALE ENDS.		
ADDITIONAL DEFECT AS OF 30/05/10		
13. P.P.82 N.E. POST HAS BEEN REMOVED DUE TO IMPACT, TOP RAIL HOLED.		

PHOTOGRAPHS CORRELATE TO NUMERICAL LIST OF DEFECTS.

**DEFECT 1.**



**DEFECT 2.**



**DEFECT 3.**



**DEFECT 4.**



**DEFECT 5.**



**DEFECT 6.**



**DEFECT 7.**



**DEFECT 8.**



**DEFECT 9.**



**DEFECT 10.**



**DEFECT 11.**



**DEFECT 12.**



**DEFECT 13.**





INSPECTION DEPARTMENT
South Bound Crash Barrier
DATE: 12/11/09

