



INSPECTION DEPARTMENT
NORTH WEST SIDE TOWER POST TENSION SURVEY
DATE: 26/05/11

SIDE TOWER POST TENSION CABLE SURVEY																																					
NORTH SIDE TOWER	WEST LEG																																				
<table border="1" style="margin: auto; border-collapse: collapse;"> <tr> <td style="width: 150px; height: 100px; vertical-align: top; text-align: center;">WEST</td> <td style="width: 300px; height: 200px; text-align: center;"> <table border="1" style="margin: auto; border-collapse: collapse;"> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> <tr> <td colspan="10" style="height: 100px;"> </td> </tr> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> </table> </td> <td style="width: 100px; height: 100px; vertical-align: middle; text-align: center;">NORTH →</td> </tr> <tr> <td style="text-align: center;">EAST</td> <td></td> <td></td> </tr> </table>		WEST	<table border="1" style="margin: auto; border-collapse: collapse;"> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> <tr> <td colspan="10" style="height: 100px;"> </td> </tr> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> </table>	1	2	3	4	5	6	7	8	9	10											1	2	3	4	5	6	7	8	9	10	NORTH →	EAST		
WEST	<table border="1" style="margin: auto; border-collapse: collapse;"> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> <tr> <td colspan="10" style="height: 100px;"> </td> </tr> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> </table>	1	2	3	4	5	6	7	8	9	10											1	2	3	4	5	6	7	8	9	10	NORTH →					
1	2	3	4	5	6	7	8	9	10																												
1	2	3	4	5	6	7	8	9	10																												
EAST																																					
<b>E1</b> intact and secure.	<b>W1</b> intact and secure.																																				
<b>E2</b> intact and secure.	<b>W2</b> intact and secure.																																				
<b>E3</b> intact and secure.	<b>W3</b> intact and secure.																																				
<b>E4</b> intact and secure.	<b>W4</b> intact and secure.																																				
<b>E5</b> intact and secure.	<b>W5</b> intact and secure.																																				
<b>E6</b> intact and secure.	<b>W6</b> intact and secure.																																				
<b>E7</b> intact and secure.	<b>W7</b> intact and secure.																																				
<b>E8</b> intact and secure.	<b>W8</b> intact and secure.																																				
<b>E9</b> intact and secure.	<b>W9</b> intact and secure.																																				
<b>E10</b> intact and secure.	<b>W10</b> intact and secure.																																				
<p>All post tension cables remain in a satisfactory condition , floor dry at time of inspection. No signs of moisture/water evident. No strand breakages evident.</p>																																					
<b>INSPECTOR:</b>	<b>DATE: 26/05/11.</b>																																				
<b>INSPECTOR:</b>	<b>DATE: 26/05/11.</b>																																				