



Wires cut at both ends

Photographs of redundant lighting standard supply conduit that requires to be removed from north face of cross girder at PP 70 North East side of only.



PP 70 north on centre grillage .
conduit unsupported hanging down.

Defect removed by engineer at time of Inspection. Date : 13/06/10.



INSPECTION DEPARTMENT
Mainspan upper front Pl. Redundant conduit.
DATE. 13/06/10