

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:41

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 28/07/1997

Inspector:

Defects: NONE

Remarks:

Action Required: None

Works Completed: Yes

Record: 29 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



Structure List



08:40

Structure No: 730T

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 12/05/1998

Inspector:

Defects: NONE

Remarks:

Action Required: None

Works Completed: Yes

Record: 28 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:40

Structure No: 7301 Element: SIDE SPAN NORTH
 Location: WEST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections

Date: 28/09/1995 Inspector: Defects: NONE

Remarks:

Action Required: None Works Completed: Yes

Record: 27 of 29

STRUCTURE REPORTS MENU

Defect Reports
 Select Element (Complete List)
 Select Element and Defect

General Report
 Input/Print General Report
 Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:40

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 02/10/2006

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required

Works Completed

Record: 26 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:39

Structure No: 7301 Element: SIDE SPAN NORTH
 Location: WEST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections

Date: 20/03/2007 Inspector: Defects: NONE

Remarks:

Action Required: Works Completed:

Record: 25 of 29

STRUCTURE REPORTS MENU

- Defect Reports
- Select Element (Complete List)
- Select Element and Defect
- General Report
- Input/Print General Report
- Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:39

Structure No: 7301
 Location: WEST
 Item: MAIN LINK
 Criticality:
 Element: SIDE SPAN NORTH
 Part: N. MAIN TOWER
 Inspection Freq: 6 Monthly
 Vulnerability:
 Inspector:
 Defects: NONE
 Action Required:
 Works Completed:
 Record: 24 of 29

Record of Inspections

Date: 01/10/2001
 Remarks:
 Action Required:
 Works Completed:
 Record: 24 of 29

STRUCTURE REPORTS MENU

- Defect Reports
- Select Element (Complete List)
- Select Element and Defect
- General Report
- Input/Print General Report
- Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Plans

Structure List



08:38

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 28/03/2005

Inspector: []

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required

Works Completed

Record: 23 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:38

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 23/10/2002

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required

Works Completed

Record: 22 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos

View Plans

Structure List

Exit

08:38

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 22/04/2008

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 21 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:37

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 08/01/2004

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 20 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos

View Plans

Structure List

Exit

08:37

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 30/08/2004

Inspector: [Name]

Defects: NONE

Remarks:

[Large empty text area for remarks]

Action Required

Works Completed

Record: 19 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 08:36

Structure No: 7301
 Location: WEST
 Item: MAIN LINK
 Criticality:
 Element: SIDE SPAN NORTH
 Part: N. MAIN TOWER
 Inspection Freq: 6 Monthly
 Vulnerability:
 Inspector:
 Defects: NONE

Record of Inspections
 Date: 18/04/2005
 Remarks:
 Action Required:
 Works Completed:
 Record: 18 of 29

STRUCTURE REPORTS MENU

- Defect Reports
- Select Element (Complete List)
- Select Element and Defect
- General Report
- Input/Print General Report
- Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM Photo List



Structure List



08:36

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 05/02/2005

Inspector: [Name]

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required

Works Completed

Record: 17 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element [Complete List]

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:35

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 08/11/2006

Inspector: NONE

Defects: NONE

Remarks:

General Information: New Gravity Fed Lubrication System Installed At Main Link. Old System Removed.

Action Required

Works Completed

Record: 16 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:35

Structure No: 7301

Location:

WEST

Item:

MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 17/10/2007

Inspector: E.H.

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 15 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:34

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 15/08/2008

Inspector: [Redacted]

Defects: NONE

Remarks:

[Large empty text area for remarks]

Action Required

Works Completed

Record: 14 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:34

Structure No: 730T

Location:

WEST

Item:

MAIN LINK

Criticality:



Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 10/02/2009

Inspector:

Defects: NONE

Remarks:

Action Required:

Works Completed:

Record: 13 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:33

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 03/08/2009

Inspector: NONE

Defects: NONE

Remarks:

Remarks text area

Action Required

Action Required dropdown

Works Completed

Works Completed progress bar

Record: 12 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:33

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 09/02/2010

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 11 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:32

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 22/06/2010

Inspector: [REDACTED]

Defects: NONE

Remarks:

[REDACTED]

Action Required

[REDACTED]

Works Completed

[REDACTED]

Record: 10 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

08:32

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 11/02/2011

Inspector: NONE

Defects: NONE

Remarks:

Remarks: [Empty text area]

Action Required

[Empty dropdown menu]

Works Completed

[Empty dropdown menu]

Record: 9 of 29

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



Structure List



08:28

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 19/10/2011

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 3 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:27

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

WEST

MAIN LINK



Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 18/04/2012

Inspector: [redacted]

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 14 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:27

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 18/10/2012

Inspector: T Slm

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 6 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:26

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 28/03/2016

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 5 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:26

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 06/02/2014

Inspector: []

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required

Works Completed

Record: 4 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM Photo List



View Photos



View Plans

Structure List



Exit

08:25

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 02/07/2014

Inspector: [redacted]

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required

Works Completed

Record: 1 3 of 29

STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** Photo List View Photos View Plans Structure List Exit 08:25

Structure No: 7301 Element: SIDE SPAN NORTH
 Location: WEST Part: N. MAIN TOWER
 Item: MAIN LINK Inspection Freq: 6 Monthly
 Criticality: Vulnerability:

Record of Inspections

Date: 28/02/2015 Inspector: Defects: NONE

Remarks:

Action Required: Works Completed:

Record: 2 of 29

STRUCTURE REPORTS MENU

- Defect Reports
- Select Element (Complete List)
- Select Element and Defect
- General Report
- Input/Print General Report
- Defects Report - this structure

The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

08:24

Structure No: 7301

Location: WEST

Item: MAIN LINK

Criticality:

WEST

MAIN LINK



Element: SIDE SPAN NORTH

Part: N. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

Record of Inspections

Date: 25/08/2015

Inspector:

Defects: NONE

Remarks:

Action Required:

Works Completed:

Record: 1 of 29

STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure