

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:54

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 29/05/1997

Inspector:

Defects: NONE

Remarks:

Action Required: None

Works Completed: Yes

Record: 14 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:54

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 08/06/1993

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required: None

Works Completed: Yes

Record: 27 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:54

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 13/06/2006

Inspector: [ ]

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required

Works Completed

Record: 26 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:53

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 30/05/2001

Inspector: [ ]

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required

Works Completed

Record: 25 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:53

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 28/11/2001

Inspector:

Defects: NONE

Remarks:

Remarks area (empty)

Action Required

Action Required dropdown

Works Completed

Works Completed dropdown

Record: 24 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:52

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 09/06/2002

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 23 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:52

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 08/12/2002

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required

Works Completed

Record: 22 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:51

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 30/07/2006

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required

Works Completed

Record: 21 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure



# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:50

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 13/04/2004

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required

Works Completed

Record: 20 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



Structure List



10:48

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 15/11/2004

Inspector: [ ]

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required



Works Completed



Record: 19 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:48

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 13/05/2005

Inspector: Inspector: Defects: NONE

Remarks:

Remarks: [Empty text area]

Action Required

Works Completed

Record: 18 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 10:48

Structure No: 7306  
 Location: EAST  
 Item: MAIN LINK  
 Criticality:   
 Element: SIDE SPAN SOUTH  
 Part: S. MAIN TOWER  
 Inspection Freq: 6 Monthly  
 Vulnerability:   
 Inspector:   
 Defects: NONE  
 Action Required:   
 Works Completed:   
 Record: 17 of 28

## Record of Inspections

Date: 02/03/2006  
 Remarks:   
 Action Required:   
 Works Completed:   
 Record: 17 of 28

## STRUCTURE REPORTS MENU

- Defect Reports
- Select Element (Complete List)
- Select Element and Defect
- General Report
- Input/Print General Report
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:48

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 18/12/2006

Inspector: [ ] Defects: NONE

Remarks:

General Information: New Gravity Fed Lubrication System Installed At Main Link. Old System Removed.

Action Required

Works Completed

Record: 16 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:47

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 21/11/2007

Inspector:

Defects: NONE

Remarks:

Remarks area

Action Required

Works Completed

Record: 15 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:46

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 29/09/2008

Inspector:

Defects: NONE

Remarks:

Remarks area

Action Required

Works Completed

Record: 14 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:46

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 17/08/2006

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 13 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure



# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



Structure List



10:42

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 20/08/2006

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 12 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List

Exit

10:41

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 16/02/2016

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 11 of 28

## STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:35

Structure No: 7306

Location:

EAST

MAIN LINK

Element: SIDE SPAN SOUTH

Part:

S. MAIN TOWER

Item:

MAIN LINK

Inspection Freq:

6 Monthly

Criticality:

Vulnerability:

## Record of Inspections

Date: 20/08/2016

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 10 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List View Photos View Plans Structure List Exit 10:34

Structure No: 7306  
 Location: EAST  
 Item: MAIN LINK  
 Criticality:   
 Element: SIDE SPAN SOUTH  
 Part: S. MAIN TOWER  
 Inspection Freq: 6 Monthly  
 Vulnerability:   
 Inspector:   
 Defects: NONE

## Record of Inspections

Date: 03/03/2011

Remarks:

Action Required   
 Works Completed

Record: 9 of 28

## STRUCTURE REPORTS MENU

- Defect Reports
- Select Element (Complete List)
- Select Element and Defect
- General Report
- Input/Print General Report
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



Structure List



Exit

10:34

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 18/11/2011

Inspector: T

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 8 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:33

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 08/05/2012

Inspector: NONE

Defects: NONE

Remarks:

Remarks field (empty)

Action Required:

Action Required dropdown menu

Works Completed:

Works Completed dropdown menu

Record: 7 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:33

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 20/11/2012

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required

Action Required dropdown

Works Completed

Works Completed dropdown

Record: 6 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure





# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:32

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:



Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 09/02/2014

Inspector:

Defects: NONE

Remarks:

Remarks text area

Action Required

Action Required dropdown

Works Completed

Works Completed dropdown

Record: 4 of 28

Navigation icons

## STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:32

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 01/03/2014

Inspector: [Name]

Defects: NONE

Remarks:

[Empty text area for remarks]

Action Required

Works Completed

Record: 3 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:31

Structure No: 7306

Location: EAST

Item: MAIN LINK

Criticality:

Element: SIDE SPAN SOUTH

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 16/03/2016

Inspector: NONE

Defects: NONE

Remarks:

Remarks field (empty)

Action Required

Works Completed

Record: 2 of 28

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/10/2016

ESM

Photo List

View Photos

View Plans

Structure List

Exit

10:31

Structure No: 7306  
 Location: EAST  
 Item: MAIN LINK  
 Criticality:   
 Element: SIDE SPAN SOUTH  
 Part: S. MAIN TOWER  
 Inspection Freq: 6 Monthly  
 Vulnerability:   
 Inspector:   
 Defects: NONE  
 Date: 09/10/2016

### Record of Inspections

Remarks:   
 Action Required:   
 Works Completed:   
 Record: 1 of 28

## STRUCTURE REPORTS MENU

Defect Reports

Select Element (Complete List)

Select Element and Defect

General Report

Input/Print General Report

Defects Report - this structure