

Revised LIST OF SOUTH BOUND CRASH BARRIER DEFECTS

	COMPLETED	
	NAME	DATE
North East Side Span		
1. P.P. 12 N.E. MALE END HOLED.		
2. P.P. 19-20 N.E. BENT POST (PREVIOUSLY RECORDED).		
North East Main Span		
3. P.P. 56 N.E. MALE END HOLED (UNDERSIDE).		
4. P.P. 62 N.E. MALE END HOLED (UNDERSIDE).		
5. P.P. 86 N.E. POST BASE CRACKED.		
6. P.P.88 N.E. POST BASE CRACKED (FOUR SIDES OF BASE).		
South East Main Span		
7. P.P. 68 S.E. MALE END HOLED (UNDERSIDE).		
8. P.P. 62 S.E. POST BASE CRACKED.		
South East Side Span		
9. P.P. 30 S.E. MALE END SHEARED (OUTSTANDING).		
10. P.P. 28 S.E. MALE END HOLED.		
11. P.P. 22 S.E. POST DAMAGED/WELD BROKEN (OUTSTANDING).		
12. P.P. 12 S.E. REPLACE MALE & FEMALE ENDS.		

PHOTOGRAPHS CORRELATE TO NUMERICAL LIST OF DEFECTS.

DEFECT 1.



DEFECT 2.



DEFECT 3.



DEFECT 4.



DEFECT 5.



DEFECT 6.



DEFECT 7.



DEFECT 8.



DEFECT 9.



DEFECT 10.



DEFECT 11.



DEFECT 12.

