





INSPECTION DEPARTMENT
N.W. . NW
DATE: 2014.05.01.

P.P. 96
(EVEN)

P.P. 95
(ODD)

P.P.
(EVEN)



XGIRDER

XGIRDER

XGIRDER

STRINGER
No.4


STRINGER
No.3

STRINGER
No.2

STRINGER
No.1

PANEL BREAK


PANEL BREAK



WELD. 120mm.

NORTH WEST TROUGH WELD SURVEY

WELD



Paint blistered at this trough. Appears to be water bubble. Slight area of teardrop staining on face.

