


At the request of the maintenance manager, an inspection was carried out on the above date.

Inspection was required due an accident at cross-over 3 south bull nose on the east side (southbound) on 30/12/09 at 16:50hrs.

On inspection it was found that there were five grillage bars bent and sheared at top connection points, with minor paint damage to hollow section.

All bars are secure at bottom welds and are projecting inwards (away from traffic).

Grillage bars remain in a relative safe condition, until proper repairs can be carried out.



Bridge Inspectors

G:\dd\t&p\rnmmd\branch8\FRB FOI\2. Inspection Records - Main Cable, Cable Anchorages\FETA inspection records for Suspended Span - FOI - Sheena\Mainspan\Independent Inspections\X over 3 Bullnose Damage 05.01.10.doc