

General Inspection Report

(BC15)

REPORT No.8

VIADUCT INTERNAL

DATE: 28/01/1997 TO 29/01/1997

The Four viaduct internals (Box Girders) North East, North West, South East and South West were visually inspected and with exception of a few minor defects (as noted in individual inspection reports) were found to be in a satisfactory condition