




INSPECTION DEPARTMENT  
 Combe plate weekly survey sheet  
 DATE. 2015.05.04.



Comments. :  
 On the Northbound Carriageway (West Side) NW2 – movement/noise evident when heavy vehicles pass over  
 On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over  
 On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out  
 On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over  
 Southbound Carriageway SE2 – there is slight movement on the west side.

Inspectors. : ..... Date.: .....



<b>INSPECTION DEPARTMENT</b>
<b>Combe plate weekly survey sheet</b>
<b>DATE. 2015.05.04.</b>