



INSPECTION DEPARTMENT

MONTHLY EXPANSION  
JOINT FAILSAFE SYSTEM.  
DATE: 2015.05.19.

### Expansion Joint Failsafe System

NORTH WEST SIDE SPAN	ROCKER PLATE SPRINGS & PINS	FIXINGS	TONGUE PLATE SPRINGS & PINS
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
<b>NORTH EAST SIDE SPAN</b>			
S.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	<b>CRACKED SPRING - REMAINS IN TENSION &amp; SECURE</b>
S.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
<b>NORTH WEST MAIN SPAN</b>			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
<b>NORTH EAST MAIN SPAN</b>			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
<b>SOUTH WEST SIDE SPAN</b>			
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
<b>SOUTH EAST SIDE SPAN</b>			
S.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
<b>SOUTH WEST MAIN SPAN</b>			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
<b>SOUTH EAST MAIN SPAN</b>			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.

Signed by Inspector :

**All defective springs recorded 2015.04.21. replaced since last inspection. New defective spring found this inspection.**