




INSPECTION DEPARTMENT
Main Span North West Crash barrier / Handrail.
DATE. 06.01.15

### MAIN SPAN NORTH (WEST)




#### Relevant information:

- Top Rail. -
- Post No1.-
- Post No2.-
- Post No3.-
- Post No4.-
- Post No5.-
- Post No6.-
- Post No7.-
- Post No8.-
- Post No9.-
- Post No10.-
- Post No11.-
- Post No12.- Bottom weld cracked East & West faces
- Bottom Rail.-
- Grillage.-



INSPECTION DEPARTMENT
Main Span North West Crash barrier / Handrail.
DATE. 06.01.15

MAIN SPAN NORTH (WEST)




Relevant information:

- Top Rail. -
- Post No1.-
- Post No2.-
- Post No3.-
- Post No4.-
- Post No5.-
- Post No6.-
- Post No7.-
- Post No8.-
- Post No9.-
- Post No10.- Slight impact damage – welds secure, dentation evident
- Post No11.-
- Post No12.-
- Bottom Rail.-
- Grillage.-



INSPECTION DEPARTMENT
Main Span North West Crash barrier / Handrail.
DATE. 06.01.15

MAIN SPAN NORTH (WEST)




Relevant information:

- Top Rail. - New detail expansion joint – bolt pulled through PP70
- Post No1.-
- Post No2.-
- Post No3.-
- Post No4.-
- Post No5.-
- Post No6.-
- Post No7.-
- Post No8.-
- Post No9.-
- Post No10.-
- Post No11.-
- Post No12.-
- Bottom Rail.-
- Grillage.-



INSPECTION DEPARTMENT
Main Span North West Crash barrier / Handrail.
DATE. 06.01.15

### MAIN SPAN NORTH (WEST)




#### Relevant information:

- Top Rail. -
- Post No1.-
- Post No2.-
- Post No3.-
- Post No4.-
- Post No5.-
- Post No6.-
- Post No7.-
- Post No8.-
- Post No9.-
- Post No10.-
- Post No11.- Bottom weld has come away from bottom rail – currently plated either side
- Post No12.- Bottom weld to bottom rail cracked all the way round – plate required
- Bottom Rail.- Top of rail at post no. 12 corroded right through
- Grillage.-



INSPECTION DEPARTMENT
Main Span North West Crash barrier / Handrail.
DATE. 06.01.15

MAIN SPAN NORTH (WEST)




Relevant information:

- Top Rail. - New detail expansion joint 2 no. set screws missing
- Post No1.-
- Post No2.-
- Post No3.-
- Post No4.-
- Post No5.-
- Post No6.-
- Post No7.-
- Post No8.-
- Post No9.-
- Post No10.-
- Post No11.-
- Post No12.-
- Bottom Rail.-
- Grillage.-



INSPECTION DEPARTMENT
Main Span North West Crash barrier / Handrail.
DATE. 06.01.15

MAIN SPAN NORTH (WEST)



Relevant information:

- Top Rail. -
- Post No1.-
- Post No2.-
- Post No3.-
- Post No4.-
- Post No5.-
- Post No6.-
- Post No7.-
- Post No8.-
- Post No9.-
- Post No10.-
- Post No11.-
- Post No12.-
- Bottom Rail.- Post no. 12 holed on top section of bottom rail south side of post
- Grillage.-



<b>INSPECTION DEPARTMENT</b>
<b>Main Span North West Crash barrier / Handrail.</b>
<b>DATE. 06.01.15</b>



<b>INSPECTION DEPARTMENT</b>
<b>Main Span North West Crash barrier / Handrail.</b>
<b>DATE. 06.01.15</b>