



Forth Estuary Transport Authority

INSPECTION DATE. : 17/03/08

MAINS PAN (WEST) BANGING BILLET LOCATIONS.

	SOUTH. WEST.		NORTH. WEST.
PP. 46.	SATISFACTORY	PP. 100.	SATISFACTORY
PP. 48.	SATISFACTORY	PP. 98.	BILLET No1. GAP 8-10mm
PP. 50.	SATISFACTORY	PP. 96.	SATISFACTORY
PP. 52.	BILLETS 1,2,3 &4 NOISY.	PP. 94.	SATISFACTORY
PP. 54.	SATISFACTORY	PP. 92.	SATISFACTORY
PP. 56.	SATISFACTORY	PP. 90.	SATISFACTORY
PP. 58.	SATISFACTORY	PP. 88.	SATISFACTORY
PP. 60.	BILLETS 1,2&3 & NOISY	PP. 86.	SATISFACTORY
PP. 62.	BILLETS 2,3&4 & NOISY	PP. 84.	SATISFACTORY
PP. 64.	SATISFACTORY	PP. 82.	SATISFACTORY
PP. 66.	BILLETS 1,2,3 &4. GAPS 3-12MM .	PP. 80.	SATISFACTORY
PP. 68.	BILLET No1. NOISY	PP. 78.	SATISFACTORY
PP. 70.	BILLETS 2&3 NOISY	PP. 76.	BILLETS 2&3. GAPS 2-3mm
PP. 72.	SATISFACTORY	PP. 74.	BILLET No 2. NOISY.
PP. 74.	BILLETS 1,2,3 &4 NOISY.	PP. 72.	SATISFACTORY
PP. 76.	SATISFACTORY	PP. 70.	SATISFACTORY
PP. 78.	SATISFACTORY	PP. 68.	BILLETS 2&3 GAPS 8-10mm
PP. 80.	BILLET No2 NOISY	PP. 66.	SATISFACTORY
PP. 82.	SATISFACTORY	PP. 64.	SATISFACTORY
PP. 84.	SATISFACTORY	PP. 62.	SATISFACTORY
PP. 86.	SATISFACTORY	PP. 60.	BILLETS 1&2 GAPS. 3-5mm
PP. 88.	BILLET No3 NOISY	PP. 58.	BILLETS 1&2 GAPS. 4-6mm
PP. 90.	SATISFACTORY	PP. 56.	BILLETS No3 APS 4 – 6mm
PP. 92.	BILLETS 1&2 NOISY	PP. 54.	BILLETS No 2 &3GAPS 4 – 6 mm
PP. 94.	BILLET No 1 PACKING REQ.	PP. 52.	SATISFACTORY
PP. 96.	BILLETS 1 &2 NOISY	PP. 50.	SATISFACTORY
PP. 98.	SATISFACTORY	PP. 48.	BILLETS No 2 &3GAPS 3-5mm
PP. 100.	BILLET No 3. GAP 3-5 mm	PP. 46.	SATISFACTORY

*** Priority 1. ***

** Priority 2. ** *** Priority 3. ***

Although the mating faces between the billet top and stringer soffit have gaps of various sizes, all remain relatively quiet. It is possible that deck levels may have dropped & packing may required at billet locations indicated.