

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:26

Structure No: 7305

Location: WEST

Item: MAIN LINK

Criticality:



Element: MAIN SPAN

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 26/09/1997

Inspector: [ ]

Defects: NONE

Remarks:

Found To Be Satisfactory

Action Required: None

Works Completed: Yes

Record: 27 of 27

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:26

Structure No: 7305

Location: WEST

Item: MAIN LINK

Criticality:



Element: MAIN SPAN

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 18/05/1995

Inspector:

Defects: NONE

Remarks:

Action Required: None

Works Completed: Yes

Record: 26 of 27

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:25

Structure No: 7305

Location:

WEST

Item:

MAIN LINK

Criticality:



Element: MAIN SPAN

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 29/11/1995

Inspector: G. J.

Defects: NONE

Remarks:

Action Required: None

Works Completed

No Action

Record: 25 of 27

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016

ESM

Photo List



View Photos



View Plans

Structure List



Exit

10:25

Structure No: 7305

Location: WEST

Item: MAIN LINK

Criticality:



Element: MAIN SPAN

Part: S. MAIN TOWER

Inspection Freq: 6 Monthly

Vulnerability:

## Record of Inspections

Date: 28/08/2006

Inspector:

Defects: NONE

Remarks:

Action Required

Works Completed

Record: 14 24 27 of 27

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List Structure List 10:25

Structure No: 7305 Element: MAIN SPAN  
Location: WEST Part: S. MAIN TOWER  
Item: MAIN LINK Inspection Freq: 6 Monthly  
Criticality: Vulnerability:

**Record of Inspections**  
Inspector: [ ] Defects: NONE  
Date: 28/03/2001  
Remarks: [ ]  
Action Required [ ] Works Completed [ ]  
Record: 14 23 27 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure



# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List Structure List 10:24 Exit

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**

Date: 23/04/2002 Inspector: Defects: NONE

Remarks:

Action Required Works Completed

Record: 21 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016       10:24

Structure No: 7305  
 Location: WEST  
 Item: MAIN LINK  
 Criticality:

Element: MAIN SPAN  
 Part: S. MAIN TOWER  
 Inspection Freq: 6 Monthly  
 Vulnerability:

**Record of Inspections**

Date: 19/11/2002  
 Inspector:   
 Defects: NONE  
 Action Required:   
 Works Completed:

Remarks: Satisfactory At Time Of Inspection.

Record: 20 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure



# The Forth Road Bridge Maintenance Program

19/02/2016 ESM 10:22

Photo List Structure List View Plans Exit

View Photos

Structure No: 7305 Element: MAIN SPAN

Location: WEST Part: S. MAIN TOWER

Item: MAIN LINK Inspection Freq: 6 Monthly

Criticality: Vulnerability:

**Record of Inspections**

Date: 24/06/2008 Inspector: Defects: NONE

Remarks:

Action Required Works Completed

Record: 19 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016     10:21

View Photos View Plans

Structure No: 7305 Element: MAIN SPAN

Location: WEST Part: S. MAIN TOWER

Item: MAIN LINK Inspection Freq: 6 Monthly

Criticality: Vulnerability:

**Record of Inspections**

Date: 26/11/2006 Inspector: Defects: NONE

Remarks:

Action Required Works Completed

Record: 18 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

10:20

**Structure No:** 7305      **Element:** MAIN SPAN  
**Location:** WEST      **Part:** S. MAIN TOWER  
**Item:** MAIN LINK      **Inspection Freq:** 6 Monthly  
**Criticality:**      **Vulnerability:**

**Inspector:**      **Defects:** NONE  
**Date:** 06/05/2004  
**Remarks:**   
**Action Required**      **Works Completed**

Record: 17 of 27

## STRUCTURE REPORTS MENU

- 
- 
- 
- 
- 
-



# The Forth Road Bridge Maintenance Program

19/02/2016       10:19

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**

Date: 19/08/2006 Inspector: Defects: NONE

Remarks:

Action Required: Works Completed

Record: 15 of 27

## STRUCTURE REPORTS MENU

Defect Reports

General Report

Select Element (Complete List)

Input/Print General Report

Select Element and Defect

Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/07/2016 **ESM** **Photo List** **Structure List** **Exit** 10:19

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**

Date: 18/05/2007 Inspector: Defects: NONE

Remarks: \*\*\*\* General Information. \*\*\*\* New Gravity Fed Lubrication System Installed At Main Link. Old System Removed.

Action Required Works Completed

Record: 14 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** Photo List View Plans Structure List Exit 10:18

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**  
 Inspector:   
 Defects: NONE  
 Date: 26/02/2008  
 Remarks:   
 Action Required  Works Completed   
 Record: 13 of 27

## STRUCTURE REPORTS MENU

Defect Reports   
 Select Element (Complete List)   
 Select Element and Defect   
 General Report   
 Input/Print General Report   
 Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** **Photo List** **View Photos** **View Plans** **Structure List** **Exit** 10:18

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**  
 Inspector: Defects: NONE  
 Date: 01/10/2008  
 Remarks:  
 Action Required Works Completed  
 Record: 12 of 27

## STRUCTURE REPORTS MENU

Defect Reports  
 Select Element (Complete List)  
 Select Element and Defect

General Report  
 Input/Print General Report  
 Defects Report - this structure



# The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** **Photo List** **Structure List** **Exit** 10:17

Structure No: 7305 Element: MAIN SPAN  
Location: WEST Part: S. MAIN TOWER  
Item: MAIN LINK Inspection Freq: 6 Monthly  
Criticality: Vulnerability:

**Record of Inspections**  
Inspector: Defects: NONE  
Date: 29/05/2006  
Remarks:  
Action Required Works Completed  
Record: 11 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List Structure List 10:17

View Photos View Plans Exit

Structure No: 7305  
 Location: WEST  
 Item: MAIN LINK  
 Criticality:

Element: MAIN SPAN  
 Part: S. MAIN TOWER  
 Inspection Freq: 6 Monthly  
 Vulnerability:

**Record of Inspections**

Date: 08/01/2010  
 Inspector:   
 Defects: NONE  
 Remarks:

Action Required:  Works Completed:

Record: 10 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List Structure List Exit 10:17

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**  
 Date: 18/07/2010 Inspector: Defects: NONE  
 Remarks:  
 Action Required Works Completed  
 Record: 9 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List Structure List Exit 10:16

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**

Date: 05/05/2011 Inspector: Defects: NONE

Remarks:

Action Required Works Completed

Record: 8 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM 10:16

Photo List Structure List View Photos View Plans Exit

Structure No: 7305 Element: MAIN SPAN

Location: WEST Part: S. MAIN TOWER

Item: MAIN LINK Inspection Freq: 16 Monthly

Criticality: Vulnerability:

**Record of Inspections**

Date: 14/12/2011 Inspector: Defects: NONE

Remarks:

Action Required Works Completed

Record: 7 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** **Photo List** **Structure List** **Exit** 10:16

View Photos View Plans

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**

Date: 24/06/2012 Inspector: Defects: NONE

Remarks:

Action Required Works Completed

Record: 6 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** **Photo List** **View Photos** **View Plans** **Structure List** **Exit** 10:15

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**  
 Inspector: Defects: NONE  
 Date: 01/02/2018  
 Remarks:  
 Action Required Works Completed  
 Record: 5 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** **Photo List** **Structure List** **Exit** 10:10

View Photos View Plans

Structure No: 7305  
 Location: WEST  
 Item: MAIN LINK  
 Criticality:

Element: MAIN SPAN  
 Part: S. MAIN TOWER  
 Inspection Freq: 6 Monthly  
 Vulnerability:

**Record of Inspections**

Date: 22/10/2016  
 Inspector:   
 Defects: NONE  
 Remarks:

Action Required  Works Completed

Record: 4 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure



# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List Structure List Exit 10:09

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**  
 Inspector: Defects: NONE  
 Date: 07/05/2014  
 Remarks:  
 Action Required Works Completed  
 Record: 3 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 ESM Photo List Structure List 10:09

View Photos View Plans Exit

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections**

Date: 27/10/2014 Inspector: Defects: NONE

Remarks:

Action Required Works Completed

Record: 2 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure

# The Forth Road Bridge Maintenance Program

19/02/2016 **ESM** **Photo List** **View Photos** **View Plans** **Structure List** **Exit** 10:08

Structure No: 7305 Element: MAIN SPAN  
 Location: WEST Part: S. MAIN TOWER  
 Item: MAIN LINK Inspection Freq: 6 Monthly  
 Criticality: Vulnerability:

**Record of Inspections** Inspector: Defects: NONE  
 Date: 19/05/2015  
 Remarks:  
 Action Required Works Completed  
 Record: 1 of 27

## STRUCTURE REPORTS MENU

- Defect Reports
- General Report
- Select Element (Complete List)
- Input/Print General Report
- Select Element and Defect
- Defects Report - this structure